

Wrist Strap

3A1791A

ENG

To protect electronic components from damage due to electrostatic discharge.

Part No. 112190




Important Safety Instructions

Read all warnings and instructions in this manual. Save these instructions.

NOTICE

Electrostatic discharge can damage electrical components.




Installation

NOTICE

Before handling the board, put on the static conductive wrist strap to protect against static discharge. The wrist strap must be grounded before removing the circuit board from the bag or installation of circuit board.

1. Unwrap the band end and wrap the adhesive side around your wrist.



2. Unroll the rest of the strap and remove the liner from the copper tape.
3. Attach the copper tape to the electrical ground or the metal frame of the equipment you are servicing.

Graco Inc. P.O. Box 1441 Minneapolis, MN 55440-1441

Original instructions. MM 3A1791

Copyright 2011, Graco Inc. is registered to ISO 9001



AFS - Application Fast Set
483, Avenue Lazare Ponticelli
77220 Gretz-Armainvilliers
Tel : 01 64 16 41 63 - Fax : 01 64 16 48 67
contact@afs-bicomposant.fr
www.afs-bicomposant.fr